


Circulation



Trails

- Lack of Hierarchy
- Accessibility
- Way-Finding Clarity
- Future Regional Trail
- Connections Needed

Vehicular

- Improved Access and Safety

Parking


- Quantity and Quality of Parking

Murase Plaza



- High Use Area
- Under-Utilized Amphitheater
- ADA Accessibility Challenges
- Confusing Vehicular Access
- Possible Connection to East Side
- Safety and Play Value Improvements

West



- Lighting Improvements at Field #4
- Pump Station Re-Location- Planned
- Drainage and Irrigation Equipment Conflict
- Desire for Expanded Recreational Opportunities
- Sports Field/Portable Fencing Improvements
- Desire for Infield Expansion
- Neighborhood Proximity Concerns


Park Areas

Riverfront



- Possible River Access
- Security and Safety Concerns
- Trail Improvements
- ADA Accessibility Challenges
- Neighborhood Proximity Concerns

East



- Available Area for Possible Use
- Community Garden Expanding to 120 Plots
- Off-leash Area Maintenance
- Parking Quality and Location
- Limited Pedestrian Access From West Side
- Natural Areas Benefits

Considerations